

Version Info:

1. Minimum FW Version for Update: 2.3.2 Build 20250704 Rel. 61997.
2. This firmware is fully adapted to Pharos Control v2.0.8.

Enhancements:

1. Optimized the UI layout.

Bug Fixed:

1. Fixed an issue where some configuration pages displayed abnormally.