

Version Info:

1. Minimum FW Version for Update: 1.0.4 Build 20250917 Rel. 84060.
2. Recommended Omada Controller version 5.15 or above.
3. For downloading of any firmware version, please refer to [Omada Download Center](#).

Bug fixed:

1. Fixed an issue where abnormal performance may occur.
2. Fixed an issue where creating an OWE-encrypted MLO SSID may cause an exception.

Notes:

1. This version of firmware is applied to the Omada APP v4.25 or above.