

Version Info:

1. Minimum FW Version for Update: 2.3.2 Build 20251113 Rel.54430.
2. This firmware upgrade is irreversible. Contact tp-link technical support if downgrade is required.
3. Recommended Pharos Control version 2.0.8 or above.

Enhancements:

1. Encrypted the firmware and optimized the algorithm to enhance the overall security of the firmware.