

Release Note for ER7206(UN) v2.0/v2.6/v2.20/v2.26/v2.30/v2.36 and ER7206(IN) v2.8/v2.28/v2.38

Important Notice:

No.

Version Info:

1. Applied Models:

- a) ER7206(UN) v2.0
- b) ER7206(UN) v2.6
- c) ER7206(UN) v2.20
- d) ER7206(UN) v2.26
- e) ER7206(UN) v2.30
- f) ER7206(UN) v2.36
- g) ER7206(IN) v2.8
- h) ER7206(IN) v2.28
- i) ER7206(IN) v2.38

2. Firmware Version: 2.2.7 Build 20251224 Rel.37150

3. Minimum FW Version for Update:

- a) UN v2.0: 2.2.2 Build 20250724 Rel.11109 and above
- b) UN v2.6: 2.2.2 Build 20250724 Rel.11109 and above
- c) UN v2.20: 2.2.2 Build 20250724 Rel.11109 and above
- d) UN v2.26: 2.2.2 Build 20250724 Rel.11109 and above
- e) UN v2.30: 2.2.3 Build 20250929 Rel.69818 and above
- f) UN v2.36: 2.2.3 Build 20250929 Rel.69818 and above
- g) IN v2.8: 2.2.2 Build 20250724 Rel.11109 and above
- h) IN v2.28: 2.2.2 Build 20250724 Rel.11109 and above
- i) IN v2.38: 2.2.3 Build 20250929 Rel.69818 and above

For downloading of any firmware version, please refer to [Omada Download Center](#).

4. Recommended Controller Version: 6.1

5. Recommended APP Version: No

New Features:

1. Added IPv6 URL Filtering feature.
2. LAN-to-LAN type ACL supports selecting IP Group for both source and destination.

Enhancements:

No.

Bug Fixed:

1. Fixed the issue that configuring WAN Alias causes SD-WAN disconnection.
2. Fixed the issue that abnormal Switch chips cause device malfunction.
3. Fixed the issue that DPI cannot intercept http3 traffic.

Additional Information:

No.