

Version Info:

Firmware for SG3428MP(UN) 6.30, SG3428MP(UN) 6.36, SG3428MP(BR) 6.36, SG3428MP(IN) 6.38, SG3428MP(EU) 6.36. Recommended Omada Controller V6.0.0.

Bug fixed

1. Fix the issue of IP loss caused by repeated modification of VLAN configuration by the controller.
2. Fix httpJson memory leak issue
3. Fix web reset failure issue.