

**Version Info:**

**Firmware for SG3428XMPP(UN) 1.20, SG3428XMPP(UN) 1.26. Recommended  
Omada Controller V6.0.0.**

Bug fixed

1. Fix the issue of IP loss caused by repeated modification of VLAN configuration by the controller.
2. Fix httpJson memory leak issue
3. Fix web reset failure issue.
4. Fix the issue of yellow LED lights on when PoE load exceeds 60W during initialization.