

Version Info

Firmware for SX3832MPP(UN) 1.0 and 1.6. Recommended Omada Controller V6.1.0.

Enhancements

1. Optimized client alarm notifications in Controller mode.

Bug fixed

1. Fixed an issue of port authentication anomalies during upgrade.
2. Eliminated the risk of management instability when multiple NTP servers are configured.
3. Fixed a bug causing unstable SSH connections.