

Release Note for Fusion G+(UN) v1.0/v1.6

Version Info:

1. Applied Models:

- a) Fusion G+(UN) v1.0
- b) Fusion G+(UN) v1.6

2. Firmware Version:

1.0.1 Build 20260306 Rel.30760

3. Minimum FW Version for Update:

- a) Fusion G+(UN) v1.0: 1.0.0 Build 20260208 Rel.42651
- b) Fusion G+(UN) v1.6: 1.0.0 Build 20260208 Rel.42651

For downloading of any firmware version, please refer to [Omada](#)

Download Center.

4. Recommended Controller Version:

6.2.X

5. Recommended APP Version:

5.2.X

New Features:

No.

Enhancements:

No.

Bug Fixed:

Fixed the issue that the Light Link VPN feature cannot function properly.

Additional Information:

No.