

Version Info:

Firmware for S7500-26XF6Y(UN) 1.20.

Recommended Omada Controller V6.2.10.

SHA-256 Value:

a9d0ee05b35aec3cf862be0b27139242389ad167a75cd8bdf5490c99705d37d2

SHA-512 Value:

**f2688e4149f1bb546ae06684bcb658a9d1d412a268e702c7961e663c0847f9a2c2e67
5a8b3abf23b17b3f0581abe27fd06eaf1f10aac17a0222a99252ede0044**

New Features

1. Added support for MP-BGP.
2. Added support for additional requirements under Omada Controller 6.x.
3. Added support for PIMv6 and MLD.
4. Added support for CPP packet rate limiting.
5. Added support for RPVST.

Enhancements

1. Enhanced the stability of the stacking feature.
2. Enhanced MLAG stability.
3. Strengthened device security robustness.
4. Added a system exception recovery mechanism.

Bug Fixed

1. Fixed an issue where the device could repeatedly reboot and exit abnormally when the netif reached full capacity.
2. Fixed occasional issues with MSTP in certain scenarios.
3. Fixed performance issues with the DHCP server.
4. Fixed occasional issues in the routing management module.
5. Fixed forwarding performance issues in MLAG scenarios.

6. Fixed disconnection issues during Controller adoption.

7. Optimized the performance of the 802.1X module.

Others

None.