

Version Info:

Firmware for S7500-32C(UN) 1.0.

Recommended Omada Controller Pro V1.10.20.

SHA-256 Value:

8b03817bd583662c89349864dd10926ba9d5c6d6aa3652915fae9c26f3588ed6

SHA-512 Value:

**5c60f6b5587c8776596db65afab1e5c2785e18aa0f40af94c29e87c8f0dce1d17d2d15
105ceb967207d87fc4f4d5c19352c091a47e6fcd0f5a69531e448ffd18**

New Features

1. Discontinued support for the ECSP v1 protocol. Adoption using older versions of the Controller is no longer supported in order to prevent potential security vulnerabilities.

Enhancements

1. None.

Bug Fixed

1. Fixed a memory leak issue reported by the market when using the SNMP feature.
2. Fixed an issue reported by the market where VLAN hardware could not be deleted in specific scenarios.
3. Fixed security vulnerabilities related to the connection with the Controller.

Others

1. None.