

Version Info:

1. Minimum FW Version for Update: 1.1.2 Build 20251013 Rel. 32717.
2. Recommended Omada Controller version 6.2 or above.
3. For downloading of any firmware version, please refer to [Omada Download Center](#).

Bugs Fixed

1. Fix the memory leak issue in the Radsec feature.

Note:

1. This version of firmware is applied to the Omada APP 5.2 or above.