

**Version Info:**

**This firmware is fully adapted to Omada Controller v5.15.24.**

**Minimum FW Version for Update: 1.0.1 Build 20220627 Rel. 73804, for downloading of any firmware version, please refer to Omada Download Center.**

**Bug fixed:**

1. Fixed an issue where the Mesh AP entered isolated state repeatedly in specific scenarios.

**Notes:**

1. This version of firmware is applied to the Omada APP v4.24 or above.