

Version Info:

This firmware is fully adapted to Omada Controller v5.15.24.

Minimum FW Version for Update: 1.0.0 Build 20220719 Rel. 37186, for downloading of any firmware version, please refer to Omada Download Center.

Bug fixed:

1. Fixed an issue where the Mesh AP entered isolated state repeatedly in specific scenarios.

Notes:

1. This version of firmware is applied to the Omada APP v4.24 or above.