

Version Info:

1. Minimum FW Version for Update: 1.1.3 Build 20250718 Rel. 57445
2. This firmware is fully adapted to Omada Controller v5.15.24.
3. For downloading of any firmware version, please refer to [Omada Download Center](#).

New features:

1. Added support for Multiple Bridge Auto-Pairing.

Enhancement:

1. Improved Client AP IP conflict issue in PtMP without DHCP server scenario by enabling Main AP DHCP server to allocate IP for Client APs.

Bug fixed:

1. Fixed a series of user interface issues to improve usability and consistency.
2. Fixed the issue that after hardware reset and power cycle of the Main AP, the standalone management page would require admin/admin to login before quick setup.

Notes:

1. This version of firmware is applied to the Omada APP v4.25 or above.