

Release Note for ER7406(UN) v1.0/v1.20/v1.26/v1.6

Version Info:

1. Applied Models:

- a) ER7406(UN) v1.0
- b) ER7406(UN) v1.20
- c) ER7406(UN) v1.26
- d) ER7406(UN) v1.6

2. Firmware Version:

1.3.2 Build 20260509 Rel. 24930

3. Minimum FW Version for Update:

- a) ER7406(UN) v1.0: 1.2.2 Build 20250724 Rel.11109 and above
- b) ER7406(UN) v1.20: 1.2.3 Build 20250929 Rel.69818 and above
- c) ER7406(UN) v1.26: 1.2.3 Build 20250929 Rel.69818 and above
- d) ER7406(UN) v1.6: 1.2.2 Build 20250724 Rel.11109 and above

To download any firmware version, please go to the [Omada Download Center](#).

4. Recommended Controller Version:

6.2.X

5. Recommended APP Version:

No.

New Features:

No.

Enhancements:

No.

Bug Fixed:

1. Fixed the issue that the DNS service generates DNS64 addresses for domains that don't have AAAA records.
2. Fixed the issue of configuring the port forwarding rule for a Limited IP Address, which does not take effect after a device restart.

Additional Information:

No.