

Version Info:

1. Minimum FW Version for Update: 1.6.1 Build 20260303 Rel. 12689.
2. This firmware upgrade is irreversible. Contact support if issues are encountered after the firmware upgrade.
3. Recommended Omada Controller version 6.1 or above.
4. For downloading of any firmware version, please refer to [Omada Download Center](#).

Enhancements:

1. Encrypted the firmware and optimized the algorithm to enhance the overall security of the firmware.

Bug fixed:

1. Fixed an issue where a memory leak might occur when RadSec is configured.

Notes:

1. This version of firmware is applied to the Omada APP v5.1 or above.