

# Release Note

## Important Notice:

This firmware upgrade is irreversible. Contact support if issues are encountered after the firmware upgrade.

## Version Info:

- 1. Firmware Version:** 1.3.15 Build 20260424 Rel. 11922.
- 2. Applied Model:** EAP772 2.20.
- 3. Minimum FW Version for Update:** 1.3.11 Build 20251112 Rel. 46109.
- 4. Recommended Omada Controller version:** 5.15.24.
- 5. Recommended Omada App version:** 5.0.131 (iOS) and 5.0.55 (Android).
6. For downloading any firmware version, please refer to [Omada Download Center](#).

## New Features:

1. Added support for the 6 GHz band.

## Enhancements:

1. Optimized Beacon frame broadcasting mechanism.

## Bug Fixed:

1. Fixed an issue where the iPhone16pro (iOS 26.3) could fail to obtain an IP address after roaming multiple times when MLO was enabled.