

Release Note

Important Notice:

This firmware upgrade is irreversible. Contact support if issues are encountered after the firmware upgrade.

Version Info:

1. **Firmware Version:** 1.2.0 Build 20260630 Rel. 82652

2. **Applied Model:**

- a) DR3220v-4G(EU) v1.0
- b) DR3220v-4G(EU) v1.20

3. **Recommended Omada Controller version:** 6.2.14.

4. **Recommended Omada App version:** N/A.

5. **Minimum FW Version for Update:**

- a) EU v1.0: 1.1.0 Build 20250801 Rel.81473
- b) EU v1.20: 1.1.1 Build 20250929 Rel.60007

New Features:

1. Added support for V6 Plus and DS-Lite dial-up.
2. Added support for configuring multiple DHCP IP pool ranges when operating as a DHCP server.
3. Added support for displaying DHCP-assigned client IP information when managed by a controller.
4. Added support for multi-channel configuration. Standalone configuration is supported through the local web interface when disconnected from the controller.
5. Added support for SpeedTest.
6. Added support for configuring SIP ALG ports.
7. Added support for NAT Traversal.

Enhancements:

1. Optimized device boot time.
2. Improved overall system stability and reliability.
3. Optimized menu layout and usability.
4. Improved network configuration deployment efficiency.
5. Reduced resource consumption for traffic statistics.
6. Optimized Load Balancing configuration.
7. Optimized VPN configuration experience.
8. Expanded SD-WAN capacity.
9. Enhanced compatibility, performance, and reliability of networking services.

Bug Fixed:

1. Fixed several known issues.