

Release Note

Important Notice:

This firmware upgrade is irreversible. Contact support if issues are encountered after the firmware upgrade.

Version Info:

1. **Firmware Version:** 1.2.0 Build 20260630 Rel. 83347

2. **Applied Model:**

- a) DR3650v-4G(EU) v1.0
- b) DR3650v-4G(EU) v1.20
- c) DR3650v-4G(AU) v1.0
- d) DR3650v-4G(AU) v1.20

3. **Recommended Omada Controller version:** 6.2.14.

4. **Recommended Omada App version:** 5.3.

5. **Minimum FW Version for Update:**

- a) EU v1.0: 1.1.0 Build 20250801 Rel.81753
- b) EU v1.20: 1.1.1 Build 20250929 Rel.07221
- c) AU v1.0: 1.1.2 Build 20251104 Rel.64548
- d) AU v1.20: 1.1.3 Build 20251105 Rel.45323

New Features:

- 1. Add support for V6plus/DS-Lite Dial-up.
- 2. Add support for configuring multiple segment of DHCP IP pool when acting as DHCP server.
- 3. Add support for showing a list of clients obtaining IP addresses via DHCP when adopted on controller.
- 4. Add support for multi-channel configuration, currently support entering standalone UI to configure while disconnected from controller.
- 5. Add support for SpeedTest.
- 6. Add support for configuring ports of SIP ALG.
- 7. Add support for NAT Traversal.

Enhancements:

- 1. Optimized boot up time.
- 2. Optimized system stability.
- 3. Optimized menu layout.
- 4. Optimized efficiency of Network configuration deployment.
- 5. Optimized the resource consumption of traffic statistic.
- 6. Optimized the configuration of Load Balance.
- 7. Optimized configuration logic of VPN.
- 8. Expanded SD-WAN capacity.
- 9. Enhanced device security.

Bug Fixed:

1. Fixed several known issues.