

# Release Note

## Version Info:

1. **Firmware Version:** 1.5.6 Build 20260629 Rel. 20690
2. **Applied Model:** EAP653 UR v1.0/v1.20
3. **Minimum FW Version for Update:** 1.4.2 Build 20251208 Rel. 43830
4. **Recommended Omada Controller version:** 6.1
5. **Recommended Omada App version:** 5.1
6. For downloading any firmware version, please refer to [Omada Download Center](#).

## Enhancements:

1. Improved the stability of the software upgrade process.

## Bug Fixed:

1. Fixed an issue where clients lost VLAN assignment after roaming when using Enterprise security with 802.11r.