

Release Note

Important Notice:

This firmware version does not support downgrade. If you encounter any issues after upgrading, please contact Omada Technical Support.

Version Info:

1. **Firmware Version:** 2.4.4 Build 20260630 Rel. 14398

2. **Applied Model:**

- a) ER605(UN) v2.0
- b) ER605(UN) v2.20
- c) ER605(UN) v2.26
- d) ER605(UN) v2.30
- e) ER605(UN) v2.36
- f) ER605(UN) v2.6
- g) ER605(IN) v2.28
- h) ER605(IN) v2.38
- i) ER605(IN) v2.8
- j) ER605(BR) v2.36

3. **Recommended Omada Controller version:** 6.2.14

4. **Recommended Omada App version:** NO

5. **Minimum FW Version for Update:**

- 6. a) ER605(UN) v2.0: 2.3.2 Build 20251029 Rel.12727 and above
- b) ER605(UN) v2.20: 2.3.2 Build 20251029 Rel.12727 and above
- c) ER605(UN) v2.26: 2.3.2 Build 20251029 Rel.12727 and above
- d) ER605(UN) v2.30: 2.3.2 Build 20251029 Rel.12727 and above
- e) ER605(UN) v2.36: 2.3.2 Build 20251029 Rel.12727 and above
- f) ER605(UN) v2.6: 2.3.2 Build 20251029 Rel.12727 and above
- g) ER605(IN) v2.28: 2.3.2 Build 20251029 Rel.12727 and above
- h) ER605(IN) v2.38: 2.3.2 Build 20251029 Rel.12727 and above
- i) ER605(IN) v2.8: 2.3.2 Build 20251029 Rel.12727 and above
- j) ER605(BR) v2.36: 2.3.2 Build 20251029 Rel.12727 and above

New Features:

No.

Enhancements:

- 1. Improved overall system stability and reliability.
- 2. Updated the Geo-IP database to improve location accuracy for certain IP addresses.
- 3. Enhanced OpenVPN, WireGuard, VPN user management, and network service reliability.
- 4. Improved compatibility and stability of the Standalone management interface across supported browsers.

Bug Fixed:

1. Fixed some known issues.