

Release Note

Version Info:

1. **Firmware Version:** 5.1.4 Build 20260203 Rel. 10151
2. **Applied Model:** EAP110-Outdoor v3.0/v3.20
3. **Minimum FW Version for Update:** 5.1.2 Build 20250709 Rel. 66838
4. **Recommended Omada Controller version:** 5.7
5. **Recommended Omada App version:** 4.10
6. For downloading any firmware version, please refer to [Omada Download Center](#).

Enhancements:

1. Optimized CLI functionality.

Bug Fixed:

1. Fixed an issue where repeatedly using the `show syslog` command caused high CPU usage.
2. Fixed an issue where the SSID could not be discovered after rebooting the device in Repeater mode, as the ath interface failed to come up properly.
3. Fixed an issue where the Repeater mode did not support backward compatibility with WPA encryption.
4. Fixed abnormal configuration issues (such as dual-band settings) on the Quick Setup page.
5. Fixed an issue where the login page did not automatically appear after setting a new password.
6. Fixed an issue where Secondary DNS displayed as `0.0.0.0` when managed by OC.
7. Fixed an issue where login timeout was incorrectly triggered during Omada APP management.