

Release Note

Version Info:

1. **Firmware Version:** 1.2.1 Build 20260612 Rel. 14879
2. **Applied Model:** EAP615GP-Wall 1.0/1.20
3. **Minimum FW Version for Update:** 1.0.9 Build 20250731 Rel. 40099.
4. **Recommended Omada Controller version:** 6.1.0.19.
5. **Recommended Omada App version:** 5.0.
6. For downloading any firmware version, please refer to [Omada Download Center](#).

Enhancements:

1. Enhanced the VoIP feature to support outbound calls to the numbers 86 and 87.
2. Enhanced system stability.

Bug Fixed:

1. Fixed an issue where only the first Service ID took effect when multiple Service IDs were added to a custom Bonjour Service.
2. Fixed an issue where editing a MAC Filter Group might cause the AP to go offline when multiple SSIDs were bound to the same MAC Filter Group.
3. Fixed an issue where enabling AI Roaming could occasionally affect AP stability.