

Release Note

Version Info:

1. **Firmware Version:** 5.1.4 Build 20260203 Rel. 10151
2. **Applied Model:** EAP110 v4.0/v4.20
3. **Minimum FW Version for Update:** 5.1.2 Build 20250709 Rel. 66838
4. **Recommended Omada Controller version:** 5.7
5. **Recommended Omada App version:** 4.10
6. For downloading any firmware version, please refer to [Omada Download Center](#).

Enhancements:

1. Optimized CLI functionality.

Bug Fixed:

1. Fixed an issue where repeatedly using the `show syslog` command caused high CPU usage.
2. Fixed abnormal configuration issues (such as dual-band settings) on the Quick Setup page.
3. Fixed an issue where the login page did not automatically appear after setting a new password.
4. Fixed an issue where Secondary DNS displayed as `0.0.0.0` when managed by OC.
5. Fixed an issue where login timeout was incorrectly triggered during Omada APP management.