

Release Note

Important Notice:

This firmware upgrade is irreversible. Contact support if issues are encountered after the firmware upgrade.

Version Info:

1. **Firmware Version:** 1.2.11 Build 20260723 Rel.41567

2. **Applied Model:**

- a) ER706W(US) 1.0
- b) ER706W(US) 1.6
- c) ER706W(US) 1.20
- d) ER706W(US) 1.26
- e) ER706W(US) 1.30
- f) ER706W(US) 1.36

3. **Recommended Omada Controller version:** 6.2.14

4. **Recommended Omada App version:** 5.3

5. **Minimum FW Version for Update:**

- a) US 1.0: 1.2.1 Build 20250821 Rel.80909
- b) US 1.6: 1.2.1 Build 20250821 Rel.80909
- c) US 1.20: 1.2.1 Build 20250821 Rel.80909
- d) US 1.26: 1.2.1 Build 20250821 Rel.80909
- e) US 1.30: 1.2.2 Build 20250928 Rel.80480
- f) US 1.36: 1.2.2 Build 20250928 Rel.80480

For downloading any firmware version, please refer to [Omada Download Center](#).

New Features:

- 1. None.

Enhancements:

- 1. None.

Bug Fixed:

- 1. Fix some security issues and enhance the security of the equipment.