

Release Note

Version Info:

1. Firmware Version: 3.0.29 Build 20260804 Rel.4241

2. Applied Model:

a) SG3210XHP-M2(UN) 3.0

b) SG3210XHP-M2(UN) 3.6

c) SG3210XHP-M2(IN) 3.8

3. Recommended Omada Controller version: 6.2.10.

4. Recommended Omada App version: N/A

5. For downloading any firmware version, please refer to [Omada Download Center](#).

Bug Fixed:

1. Fixed an issue that caused reduced Layer 3 forwarding throughput.