

Release Note

Version Info:

1. Firmware Version: 1.20.7 Build 20260804 Rel.4241

2. Applied Model:

a) SG3210X-M2(UN) 1.20

b) SG3210X-M2(UN) 1.26

3. Minimum FW Version for Update:

1.20.0 Build 20251205 Rel.67586

4. Recommended Omada Controller version: 6.2.10.

5. Recommended Omada App version: N/A

6. For downloading any firmware version, please refer to [Omada Download Center](#).

Bug Fixed:

1. Fixed an issue that caused reduced Layer 3 forwarding throughput.