

Release Note

Important Notice:

This firmware upgrade is irreversible. Contact support if issues are encountered after the firmware upgrade.

Version Info:

1. **Firmware Version:** 2.3.10 Build 20260811 Rel.73171

2. **Applied Model:**

- a) ER7206(UN) v2.0
- b) ER7206(UN) v2.20
- c) ER7206(UN) v2.26
- d) ER7206(UN) v2.30
- e) ER7206(UN) v2.36
- f) ER7206(UN) v2.6
- g) ER7206(IN) v2.28
- h) ER7206(IN) v2.38
- i) ER7206(IN) v2.8

3. **Minimum FW Version for Update:**

- a) ER7206(UN) v2.0: 2.2.2 Build 20250724 Rel.11109 and above
- b) ER7206(UN) v2.20: 2.2.2 Build 20250724 Rel.11109 and above
- c) ER7206(UN) v2.26: 2.2.2 Build 20250724 Rel.11109 and above
- d) ER7206(UN) v2.30: 2.2.3 Build 20250929 Rel.69818 and above
- e) ER7206(UN) v2.36: 2.2.3 Build 20250929 Rel.69818 and above
- f) ER7206(UN) v2.6: 2.2.2 Build 20250724 Rel.11109 and above
- g) ER7206(IN) v2.28: 2.2.2 Build 20250724 Rel.11109 and above
- h) ER7206(IN) v2.38: 2.2.3 Build 20250929 Rel.69818 and above
- i) ER7206(IN) v2.8: 2.2.2 Build 20250724 Rel.11109 and above

4. **Recommended Omada Controller version:** 6.3.0.

5. **Recommended Omada App version:** N/A

6. For downloading any firmware version, please refer to [Omada Download Center](#).

New Features

- 1. Support intelligent abnormal event detection

Bug Fixed

1. Fixed an issue where the online detection feature did not work properly in certain scenarios.