

Release Note

Important Notice:

This firmware upgrade is irreversible. Contact support if issues are encountered after the firmware upgrade.

Version Info:

1. **Firmware Version:** 1.1.3 Build 20260422 Rel. 22528
2. **Applied Model:** EAP115-Bridge KIT 3.0/3.6/3.8
3. **Minimum FW Version for Update:** 1.1.2 Build 20260421 Rel. 13616.
4. **Recommended Omada Controller version:** 5.15.
5. **Recommended Omada App version:** 4.25.
6. For downloading any firmware version, please refer to [Omada Download Center](#).

Enhancements:

1. Optimized the Standalone web menu layout.

Additional Information:

1. Encrypted the firmware and optimized the algorithm to enhance the overall security of the firmware.