

# Release Note

## Important Notice:

This firmware upgrade is irreversible. Contact support if issues are encountered after the firmware upgrade.

## Version Info:

1. **Firmware Version:** 1.1.2 Build 20260421 Rel. 13616.
2. **Applied Model:** EAP115-Bridge KIT 3.0.
3. **Minimum FW Version for Update:** 1.0.0 Build 20250827 Rel. 67870.
4. **Recommended Omada Controller version:** 5.15.
5. **Recommended Omada App version:** 4.25.
6. For downloading any firmware version, please refer to [Omada Download Center](#).

## Enhancements:

1. Optimized the Standalone web menu layout.

## Additional Information:

1. Encrypted the firmware and optimized the algorithm to enhance the overall security of the firmware.