

Release Note

Important Notice:

This firmware upgrade is irreversible. Contact support if issues are encountered after the firmware upgrade.

Version Info:

1. **Firmware Version:** 1.3.13 Build 20260828 Rel. 12552.
2. **Applied Model:** EAP650 D120-Outdoor v1.0/v1.6/v1.20/v1.26.
3. **Minimum FW Version for Update:** 1.3.6 Build 20260306 Rel. 14246.
4. **Fully Adapted Omada Controller version:** 6.0.
5. **Fully Adapted Omada App version:** 5.0.
6. For downloading any firmware version, please refer to [Omada Download Center](#). For more information about firmware version number and fully adapted controller version, please refer to [Announcement on the Change of Omada Product Firmware Version Numbers](#).

Bug Fixed:

1. Fixed an issue where memory leaks could occur under certain scenarios.
2. Fixed an issue where the device might go offline in some scenarios after VLAN Pool or Dynamic VLAN was configured.
3. Fixed an issue where Bluetooth Console could not be disabled.
4. Fixed an issue where the assigned VLAN was lost after client roaming when Enterprise Security, Dynamic VLAN, and 11r were configured.
5. Fixed an issue where device stability could be affected under certain scenarios.