

Release Note

Version Info:

1. **Firmware Version:** 1.0.5 Build 20260814 Rel. 07240
2. **Applied Model:** EAP773 v2.0
3. **Minimum FW Version for Update:** 1.0.3 Build 20260325 Rel. 12642
4. **Recommended Omada Controller version:** 5.15.
5. **Recommended Omada App version:** 5.0.
6. For downloading any firmware version, please refer to [Omada Download Center](#).

Enhancements:

1. Optimized device stability in various scenarios.

Bug Fixed:

1. Fixed a memory leak issue that could occur in certain scenarios.
2. Fixed an issue where abnormal mDNS packets could cause unexpected device reboots.
3. Fixed an issue where clients could lose their VLAN assignment after roaming when WPA-Enterprise and 802.11r were enabled.
4. Fixed an issue where MLO traffic transmission could fail in certain scenarios.
5. Fixed several issues related to scan results and client band display.
6. Fixed an issue where IGMP packets could cause a kernel deadlock in certain scenarios.