

Release Note

Version Info:

1. **Firmware Version:** 1.6.8 Build 20260828 Rel. 13354
2. **Applied Model:** EAP655-Wall v1.0/v1.6/v1.20/v1.26/v1.36
3. **Minimum FW Version for Update:** 1.6.2 Build 20251107 Rel. 35700
4. **Fully Adapted Omada Controller version:** 6.1.
5. **Fully Adapted Omada App version:** 5.1.
6. For downloading any firmware version, please refer to [Omada Download Center](#). For more information about firmware version number and fully adapted controller version, please refer to [Announcement on the Change of Omada Product Firmware Version Numbers](#).

Enhancements:

1. Optimized overall system stability.

Bug Fixed:

1. Fixed an issue where specific mDNS packets could cause the device to hang.
2. Fixed an issue where abnormal BAR frame forwarding could impact the wireless network.
3. Fixed an issue where ECS could experience a memory leak.
4. Fixed an issue where clients could not associate with the 2.4 GHz SSID in certain scenarios.

Additional Information:

1. Adapted to the FEP platform.