

Release Note

Version Info:

1. **Firmware Version:** 1.3.13 Build 20260828 Rel. 12552
2. **Applied Model:** EAP670 v2.0/v2.6/v2.20/v2.26
3. **Minimum FW Version for Update:** 1.3.6 Build 20260306 Rel. 14246
4. **Recommended Omada Controller version:** 6.0.
5. **Recommended Omada App version:** 5.0.
6. For downloading any firmware version, please refer to [Omada Download Center](#).

Enhancements:

1. Optimized device stability in various scenarios.

Bug Fixed:

1. Fixed a memory leak issue in the ECS process that could occur in certain scenarios.
2. Fixed an issue where the device could go offline after VLAN Pool or Dynamic VLAN was configured in certain scenarios.
3. Fixed an issue where Bluetooth Console could not be disabled.
4. Fixed an issue where clients could lose their VLAN assignment after roaming when Dynamic VLAN and 802.11r were enabled on WPA-Enterprise SSIDs.