

Release Note

Version Info:

1. **Firmware Version:** 1.3.13 Build 20260828 Rel. 12552
2. **Applied Model:** EAP673 v2.0/v2.6
3. **Minimum FW Version for Update:** 1.3.9 Build 20260415 Rel. 29836
4. **Fully Adapted Omada Controller version:** 6.0.
5. **Fully Adapted Omada App version:** 5.0.
6. For downloading any firmware version, please refer to [Omada Download Center](#). For more information about firmware version number and fully adapted controller version, please refer to [Announcement on the Change of Omada Product Firmware Version Numbers](#).

Bug Fixed:

1. Fixed an issue that could cause an ECS memory leak in certain scenarios.
2. Fixed an issue where devices could go offline in certain scenarios after configuring a VLAN pool or Dynamic VLAN.
3. Fixed an issue where the Bluetooth console could not be disabled.
4. Fixed an issue where clients could lose VLAN assignment after roaming when WPA Enterprise with Dynamic VLAN and IEEE 802.11r (Fast BSS Transition) was configured.