

Bundled Firmware:

[EAP110_V1](#), [EAP110_V2](#) [EAP110_V4](#)

[EAP115_V1](#), [EAP115_V2](#) [EAP115_V4](#)

[EAP225_V1](#), [EAP225_V2](#) [EAP225_V3](#)

[EAP225-Outdoor_V1](#)

[EAP110-Outdoor_V1](#) [EAP110-Outdoor_V3](#)

[EAP245_V1](#) [EAP245_V3](#)

[EAP115-Wall_V1](#) ([EAP115-Wall](#) is suitable for EU version Only.)

[EAP225-Wall_V2](#)

[EAP320_V1](#) [EAP320_V2](#)

[EAP330_V1](#) [EAP330_V2](#)

New Feature/Enhancement:

1. Optimize the performance of Controller to manage up to 1500 EAPs.
2. Optimize the interactive process between EAP and Controller to decrease the process time.
3. Limit the entry number of client/client history/guest to 1.2 million/1.2 million /6 million.
4. Optimize display page of map and log when there are a lot of entries.

Bug Fixed:

1. Fixed the bug that CPU and memory may be highly used when Fast Roaming is enabled.
2. Fixed the bug that Omada Controller reports timeout error when adopting multiple EAPs simultaneously.

3. Fixed the bug that Controller will print all Voucher codes even only some of the codes are selected.

Notes:

1. To use Omada Controller 3.2.x new features, you need to upgrade your EAP's firmware to the corresponding version.
2. Once upgraded to this version of Omada Controller, you will NOT be able to downgrade to an earlier version.
3. Portal configuration will be lost after upgrading to Omada Controller 3.2.X from 2.4.X or earlier version.