

Bundled Firmware:

[EAP110_V1](#), [EAP110_V2](#) [EAP110_V4](#)

[EAP115_V1](#), [EAP115_V2](#) [EAP115_V4](#)

[EAP225_V1](#), [EAP225_V2](#) [EAP225_V3](#)

[EAP225-Outdoor_V1](#)

[EAP110-Outdoor_V1](#) [EAP110-Outdoor_V3](#)

[EAP245_V1](#) [EAP245_V3](#)

[EAP115-Wall_V1](#) ([EAP115-Wall](#) is suitable for EU version Only.)

[EAP225-Wall_V2](#)

[EAP235-Wall_V1](#)

[EAP230-Wall_V1](#)

[EAP320_V1](#) [EAP320_V2](#)

[EAP330_V1](#) [EAP330_V2](#)

New Feature/Enhancement:

1. Add “Select Page” feature on the voucher management page.
2. Change the default status of “Terms of Service” on default portal page to uncheck.
3. Optimize the “Free Authentication Policy” to support URL with suffixes.
4. Change the default status of new added “Free Authentication Policy” to enable.

Bug Fixed:

1. Fixed the bug that when clients disconnect from the Facebook portal, the connection time and traffic usage of these clients may be zero in the log.

2. Fixed the bug that AP may disconnect from Omada Controller when it is upgrading the firmware.
3. Fixed the bug that in some cases, the channel configuration of 2.4G frequency may show up in 5G by mistake.
4. Fixed the bug that the configuration of SSID will not be issued correctly when changing the WLAN Group on the provisioning status.

Notes:

1. To use Omada Controller 3.2.x new features, you need to upgrade your EAP's firmware to the corresponding version.
2. Once upgraded to this version of Omada Controller, you will NOT be able to downgrade to an earlier version.
3. Portal configuration will be lost after upgrading to Omada Controller 3.2.X from 2.4.X or earlier version.
4. You are recommended to create a backup before upgrading, or you will not be permitted to install this version of Omada Controller.