

Bundled Firmware:

EAP110_V1, EAP110_V2 EAP110_V4
EAP115_V1, EAP115_V2 EAP115_V4
EAP225_V1, EAP225_V2 EAP225_V3
EAP225-Outdoor_V1
EAP110-Outdoor_V1 EAP110-Outdoor_V3
EAP245_V1 EAP245_V3
EAP115-Wall_V1 (EAP115-Wall is suitable for EU version only)
EAP225-Wall_V2
EAP230-Wall_V1
EAP235-Wall_V1
EAP320_V1 EAP320_V2
EAP330_V1 EAP330_V2

Bug Fixed:

1. Upgrade Log4j to 2.17 to fix the vulnerability CVE-2021-44228 and CVE-2021-45046. Please refer to [FAQ 3255](#) for more details.

Notes:

1. To use new features on Omada Controller 3.2.X, you need to upgrade your EAP's firmware to the corresponding version.
2. The Omada Controller program needs to use the system's netstat command. If the Linux system does not have net-tools installed (which contain the netstat command), the program may not be able to run normally.
3. Support 64-bit Linux operating system including Ubuntu 14.04/16.04/17.04/18.04/Debian 9.8
4. Once upgraded to this version of Omada Controller, you will NOT able to downgrade to an earlier version.