

**Recommended Controller Software Version: Omada Controller v4.1.5 or above**

**New Feature/Enhancement:**

Improve MU-MIMO feature.

**Notes:**

1. For EAP235-Wall v1 only.
2. This version of firmware is applied to Omada APP of version 3.0.X or above.
3. This firmware is only compatible with Omada controller v4.1.5 or above. If you are using old Omada controller and need to manage EAP235-Wall, you must upgrade Omada controller to version 4.1.5 or above. You can follow [Omada Controller Upgrade Guide](#) to upgrade omada controller.