

This firmware is fully adapted Omada SDN platform but only compatible with Omada controller v4.1.5 or above.

If you are using old Omada controller and plan to upgrade firmware for EAP, then you must upgrade Omada controller as well, and please follow [Omada Controller Upgrade Guide](#) to upgrade Omada controller.

If your EAP is working standalone and its version is lower than EAP245_V3_2.20.0 build 20200423, please note that the EAP will be reset after upgrading to this firmware and you need to re-configure your EAP.

New Feature/Enhancement:

Support mesh function.

Notes:

1. For EAP245 v3 only.
2. Your device's configuration will be lost after upgrading if the version is lower than EAP245_V3_2.20.0 build 20200423. You need to re-configure your devices because some new features are not compatible with the old version. Suggest to back up your configuration before upgrading and please note the new version doesn't support to restore the old configuration file.
3. This version of firmware is applied to Omada APP of version 2.1.X or above.
4. You cannot downgrade if you upgrade from the firmware released in 2018 or earlier to this version directly.
5. This firmware is only compatible with Omada controller v4.1.5 or above. If you are using old Omada controller and plan to upgrade firmware for EAP, you must upgrade Omada controller as well, and please follow [Omada Controller Upgrade Guide](#) to upgrade Omada controller.