**Bundle Omada Controller 3.2.3.** 

**Bundled Firmware:** 

EAP110\_V1, EAP110\_V2 EAP110\_V4

EAP115\_V1, EAP115\_V2 EAP115\_V4

EAP225\_V1, EAP225\_V2 EAP225\_V3

EAP225-Outdoor\_V1

EAP110-Outdoor\_V1 EAP110-Outdoor\_V3

EAP245\_V1 EAP245\_V3

EAP115-Wall\_V1 ( EAP115-Wall is suitable for EU verison Only.)

EAP225-Wall\_V2

EAP320\_V1 EAP320\_V2

EAP330\_V1 EAP330\_V2

## New Feature/Enhancement:

1. Add "Select Page" feature on the management page of vouchers.

- 2. Change the default status of "Terms of Service" to uncheck.
- 3. Optimize the "Free Authentication Policy" to support URL with suffixes.
- 4. Optimize the UI of Backup & Restore and Starting Up page.

## **Bug Fixed:**

1. Fixed the bug that when clients disconnect from the Facebook portal, the

connection time and traffic usage of these clients may be zero in the log.

2. Fixed the bug that AP may disconnect from OC200 when it is upgrading the firmware.

3. Fixed the bug that in some cases, the channel configuration of 2.4G frequency may show up in 5G by mistake.

## Notes:

1. For OC200 (UN) v1.0 only.

2. To use new features of OC200, you need to upgrade your EAP's firmware to the corresponding version.

3. Your device's configuration won't be lost after upgrading.