

TP-Link FW Release Notes

Product Name	Archer VR1200v(IT) 1.0	
Firmware Version	1.0.0 0.8.0 v600e.0 Build 220415 Rel.16633n	
Release Date	2022.04.15	
Release purposes:		
Added features according to customer's requirements		
Change items (Include New features, feature changes, bug fix)		
No.	Description	Note
1	Feature: Upgrade openssl library to support TLS 1.2/1.3	
2	Bugfix: Fix issue of slow response to ACS enable WiFi interface command	