

Recommended Controller Software Version: Omada Controller v5.5 or above

New Features/Enhancements:

1. Added support for Mesh feature in Standalone mode
2. Added support for IPv6 ACL/URL Filtering/Guest Network.
3. Added support for IPv6 dial-up/Client address acquisition/Multicast-to-Unicast Conversion.
4. Added support for Bonjour protocol.
5. Added support for Multi RADIUS servers.
6. Added support for Packet Capture/Terminal/Traceroute.
7. Added support for “Lock to AP “ function.
8. Added support for RADIUS username report.
9. Added support for PMF function.
10. Added support for LLDP (Link Layer Discovery Protocol).
11. Added support for shared bandwidth.
12. Added support for 802.11r protocol.
13. Improve wireless stability and performance.

Bug Fixed:

1. Fixed the memory leaking issue.

Notes:

1. This version of firmware is applied to the Omada APP of version 4.10.X or above.
2. This firmware is only compatible with Omada controller v4.1.5 or above. If you are using the old Omada controller and need to manage EAP610, you must upgrade the Omada controller to version 4.1.5 or above. You can follow [Omada Controller Upgrade Guide](#) to upgrade Omada controller.