

Version Info:

Firmware for DR3650v(EU) 1.0. This firmware is fully adapted to Omada Controller V5.15.6.

Bug Fixed:

1. Fixed the issue of DSL WAN and Virtual WAN wireless client unable to access the Internet under some scenarios.
2. Fixed the issue of low-probability crash during DSL WAN retraining.

Enhancements:

1. Enhanced the Omada Config feature.