

Version Info:

Firmware for SG3428XPP-M2(UN) 1.20 and 1.26. This firmware is fully adapted to Omada Controller V5.14.

New Features:

1. Originally the device will filter the UDP traffic with source port 0 by default, this is now changed to port 9 and added support for modifying via CLI command.