Version info

Firmware for S6500-24MPP4Y(UN) 1.0. This firmware is fully adapted to Omada Pro Controller V1.10.20.

SHA-256 Value:

A9AFCB7DDCA30053C0508D06663C79844A2CB2081C807CFD1F50DAB1A3CDEA8

SHA-512 Value:

B40C699D2DE45447181F13D6028C9E1A62A9FAEF9C21AE9ACF8D48F65A9C6DEB4 AE234C67DE4C65CEEB07104794E26732A8E8C1BC27813BDF42D05D1BF816714

New features

- 1. Add support for controller adoption through M-LAG member ports.
- 2. Add support for DAD-v6 in M-LAG.

Enhancements

- 1. Enhanced stability of stack.
- 2. Improve fault recovery performance in M-LAG.

Bug fixed

- 1. Fixed the issue where static IP occasionally be lost after upgrade in controller mode.
- 2. Fixed the issue where ports fail to link up occasionally after upgrade in controller mode.
- 3. Fixed the issue where ports fail to link up occasionally under stress testing.
- 4. Fixed the issue of kernel hang occurring occasionally under stress testing.