

Version Info

Firmware for SG6428XHP(UN) 1.0. This firmware is fully adapted to Omada Controller V5.15.24.

SHA-256

2c65bb8dcc6dd8e5f2382b04e704bcca63df42a56f05038ca3ef4a97ec5fab75

SHA-512

bce321bcf396ea5d14faf2bb8eb3630d7c185848f86b0ee3302b452ffc49681504a0b6
c952b00c890946e4af1875d807ba152a6d2c6d59dc61c945cb3b2c89ce

Enhancements

1. Optimized the stability of the stacking system.

Bug fixed

1. Fixed a probabilistic packet loss issue when using the device to ping other devices.
2. Fixed a bug where the MGMT interface occasionally failed to obtain an IP address or link up properly.
3. Fixed multiple bugs related to PIM.
4. Fixed a bug that could occasionally cause device anomalies when using the Locate function on the Controller.