

## **Recommended Controller Software version: Omada Controller v5.9 or above**

### **New features/Enhancements:**

1. Improved security protection capability.

### **Bug Fixed:**

1. Fixed the issue of portal with external portal server taking effect abnormally.
2. Fixed the issue that the portal authentication page cannot be popped up in some clients.
3. Fixed the issue that Pre-Authentication Access with URL entry function works abnormally.
4. Fixed the issue that portal authentication page cannot be popped up automatically with HTTPS

Redirection enabled under certain application scenarios.

5. Fixed the issue of inaccurate downstream traffic limit by portal.
6. Fixed the issue of random disconnection between VIGI IPC and VIGI App.
7. Fixed the issue of firmware assert occurring in some scenarios.
8. Fixed the issue that the AP reboots automatically under certain application scenarios.

### **Notes:**

1. This version of firmware is applied to the Omada App v4.21 or above.