

Version Info:

1. Minimum FW Version for Update: 1.0.6 Build 20241025 Rel. 72222.
2. After upgrading this firmware, rolling back to any of the previous version is forbidden.
3. This firmware is fully adapted to Omada Controller v5.9.
4. For downloading of any firmware version, please refer to Omada Download Center.

New Features:

1. Added support for recovery mode.

Enhancements:

1. Improved overall security of the firmware.

Bug fixed:

1. Fixed an issue where downstream multicast traffic on fiber port might be routed back in specific scenarios.
2. Fixed an issue where clients periodically re-associated under Radius authentication.
3. Fixed a rare issue where VoIP calls could not be initiated in specific scenarios.
4. Fixed a Manage VLAN issue in Mesh network scenarios.

Notes:

1. This version of firmware is applied to the Omada APP 4.19 or above.