

Release Note for Festa FR365(US) v1.0/v1.6/v1.20/v1.26

Important Notice:

This is a transitional firmware for RED certification compliance which is not complied to RED certification, to fully comply to RED certification, it is recommended to upgrade to version 1.1.11 afterwards.

This firmware upgrade is irreversible. Contact Omada technical support if downgrade is required.

Version Info:

1. Applied Model:

- a) Festa FR365(US) v1.0
- b) Festa FR365(US) v1.6
- c) Festa FR365(US) v1.20
- d) Festa FR365(US) v1.26

2. Firmware Version: 1.1.10 Build 20250626 Rel.81746

3. Minimum FW Version for Update:

- a) US v1.0: 1.0.4 Build 20240319 Rel.02617 and above
- b) US v1.6: 1.0.4 Build 20240319 Rel.02617 and above
- c) US v1.20: 1.1.0 Build 20240523 Rel.71270 and above
- d) US v1.26: 1.1.0 Build 20240523 Rel.71270 and above

For downloading of any firmware version, please refer to [Download Center](#) |

[TP-Link](#).

4. Recommended Controller Version: Festa CBC V1.3

5. Recommended APP Version: No

New Features:

No.

Enhancements:

No.

Bug Fixed:

1. Changed the web login password to a strong one.
2. Updated the software signature algorithm.
3. Fixed several security issues.

Additional Information:

1. Enhanced device security.